



# CARPENTER BEE SIGNS & DAMAGE




Look UP



**"Kick Back"**- looks like someone took a paintbrush and flicked it against building. It's the chewed wood that the bees kick out to make their nest.



**Nest** - Perfectly round holes, a little bigger than a pencil diameter, will be visible behind the fascia board along the roof line.



Look DOWN



**Frass** - the wood shavings from the hole the bees made for their nest, that will be in a pile below.

If you see a visible carpenter bee nest, along with this visible damage in same area, it indicates a **wood pecker** was there chipping away trying to get at the eggs in the nest.

